



## VERTEX BD 2022 / 28.0.11 RELEASE NOTES

Release date 05-06-2022

The cumulative service pack includes all the previously released fixes for Vertex BD 2022 (28.0), and the following new fixes and improvements:

### Fixed

- |          |  |
|----------|--|
| BD-27492 | Saving an element drawing can produce an incorrect message about modifications in the file |
| BD-27579 | Floor engineering - member not supported error   |
| BD-27629 | Nogs missing above header  |
| BD-27686 | Verify Distance shows incorrect formatting for feet-inch-16th in data field                |
| BD-27767 | Crash copying something in library   |
| BD-27768 | Crash fix for editing 2D-drawing   |
| BD-27780 | Circular red tool doesn't work if the tool only slightly hits the part                     |
| BD-27788 | Dimpleslot could not be manually turned on   |
| BD-27806 | Truss side reinforcement should not act as bearing to parallel (truss) member              |
| BD-27807 | Show bearings to walls like to pieces  |
| BD-27816 | Sheet numbering fixed. Cuts were not handled properly.                                     |

### Improvement

- |          |  |
|----------|--|
| BD-27694 | Cambium values need to be converted to metric when generated by imperial BD. |
| BD-27695 | Add intersecting piece location marks to Cambium output                      |